



Entergy Nuclear South
Entergy Operations, Inc.
17265 River Road
Killona, LA 70057-3093
Tel 504 739 6715
Fax 504 739 6698
rmurill@entergy.com

Robert J. Murillo
Licensing Manager
Waterford 3

W3F1-2009-0054

October 20, 2009

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

Subject: Licensee Event Report 09-002-01
Waterford Steam Electric Station, Unit 3 (Waterford 3)
Docket No. 50-382
License No. NPF-38

Dear Sir or Madam:

Entergy is hereby submitting revised voluntary Licensee Event Report (LER) 09-002-01 for Waterford Steam Electric Station Unit 3. This report provides details associated with a shortened service life of Station Battery 'B'. The original LER had reported that the shortened service life was due to apparent manufacturing impurities. A re-examination of the issue found that no definitive cause could be determined and a revised LER was needed to provide this new information. The condition is reported herein as a voluntary report because the issue is of generic interest.

This report contains no new commitments. Please contact Robert J. Murillo at (504) 739-6715 if you have questions regarding this information.

Sincerely,


RJM/RJP

Attachment: Licensee Event Report 09-002-00

IE 22

NRR

(w/Attachment)
cc: Mr. Elmo E. Collins, Jr.
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
612 E. Lamar Blvd., Suite 400
Arlington, TX 76011-4125

NRC Senior Resident Inspector
Waterford Steam Electric Station Unit 3
P.O. Box 822
Killona, LA 70066-0751

U. S. Nuclear Regulatory Commission
Attn: Mr. N. Kalyanam
Mail Stop O-07D1
Washington, DC 20555-0001

Wise, Carter, Child & Caraway
ATTN: J. Smith
P.O. Box 651
Jackson, MS 39205

Winston & Strawn
ATTN: N.S. Reynolds
1700 K Street, NW
Washington, DC 20006-3817

Morgan, Lewis & Bockius LLP
ATTN: T.C. Poindexter
1111 Pennsylvania Avenue, NW
Washington, DC 20004

Louisiana Department of Environmental Quality
Office of Environmental Compliance
Surveillance Division
P. O. Box 4312
Baton Rouge, LA 70821-4312

R.K. West, lerevents@inpo.org - INPO Records Center

Attachment

W3F1-2009-0054

Licensee Event Report 2009-002-01

1. FACILITY NAME Waterford 3 Steam Electric Station	2. DOCKET NUMBER 05000382	3. PAGE 1 OF 4
---	-------------------------------------	--------------------------

4. TITLE
Voluntary Report: Shortened Service Life of Station Battery 'B' due to Manufacturing Impurities

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
05	22	2008	2009	002	01	10	20	2009	NA	05000
									FACILITY NAME	DOCKET NUMBER
									NA	05000

9. OPERATING MODE 6	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)											
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)								
10. POWER LEVEL 00	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)								
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)								
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)								
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)								
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)								
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)								
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input checked="" type="checkbox"/> OTHER Voluntary Report Specify in Abstract below or in NRC Form 366A									
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)										

12. LICENSEE CONTACT FOR THIS LER

FACILITY NAME Waterford 3 Steam Electric Station Robert J. Murillo	TELEPHONE NUMBER (Include Area Code) (504) 739-6715
---	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE MONTH: _____ DAY: _____ YEAR: _____
--	--

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

This is a voluntary LER to report an issue of generic interest. During Refuel 15, Station Battery 'B' [EJ] was disconnected from the bus to perform testing. On 5/16/2008, at approximately 20:00 hours, a performance test on the battery showed that battery capacity was at 86.25% of the manufacturer rating. Since the average of previous performance tests was 103.7%, a degraded battery was indicated based on the capacity dropping more than 10% from its average. Station Battery 'B' was manufactured by C&D Battery and was installed in October 1992. The rated service life of the battery is 20 years. The battery had been in-service for 15.6 years prior to the performance test on 5/16/08. A confirmatory performance discharge test on 5/22/2008 revealed the battery had prematurely aged and required replacement. Measured capacity on 5/22/2008 was 71.67%. Although not applicable in modes 5 or 6, Technical Specification Surveillance Requirement (SR) 4.8.2.1.e requires battery capacity be at least 80% of the manufacturer's rating. The plant was in Mode 6 with the Station Battery 'B' disconnected from the plant from 5/16/2008 until replaced with new LCR-33 cells manufactured by C&D Battery on 5/24/2008. A Root Cause Evaluation could not determine the cause for the Station Battery 'B' prematurely aging because the Battery Cells were disposed of prior to analysis.

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		2009	- 002	- 01		

NARRATIVE**REPORTABLE OCCURRENCE**

There is no reportable occurrence per the reporting requirements outlined in Title 10 of the Code of Federal Regulations. The condition is a voluntary LER to report an issue of generic interest.

INITIAL CONDITIONS

The plant was in Mode 6 conducting refueling operations during Refuel 15 when this apparent condition occurred. This plant condition did not contribute to this event. There were no other structures, systems, or components inoperable at the start of the event or that contributed to the event. Performance testing on Station Batteries 'A' and 'AB' demonstrated acceptable performance.

EVENT DESCRIPTION

During Refuel 15, Station Battery 'B' [EJ] was disconnected from the bus to perform testing. On 5/16/2008 at approximately 20:00 hours, Waterford 3 conducted a performance test of Station Battery 'B'. The results of the performance test showed that the battery capacity had degraded to 86.25% of the manufacturer's rating. Since the average of previous performance tests was 103.7%, a degraded battery was indicated based on the measured battery capacity dropping more than 10% of the rated capacity from its average on previous performance tests. Although not applicable in modes 5 or 6, Technical Specification Surveillance Requirement (SR) 4.8.2.1.f requires annual performance discharge tests for any battery that shows signs of degradation.

The station battery 'B' is made up of 60 individual LCUN-33 cells that were manufactured by C&D Battery and installed in October 1992. The rated service life of the battery is 20 years. The battery had been in-service for 15.6 years prior to the performance test on 5/16/08. A confirmatory performance discharge test on 5/22/2008 revealed the battery had prematurely aged and required replacement. Measured capacity on 5/22/2008 was 71.67%. Although not applicable in modes 5 or 6, Technical Specification Surveillance Requirement (SR) 4.8.2.1.e requires battery capacity be at least 80% of the manufacturer's rating.

The plant was in Mode 6 with the Station Battery 'B' disconnected from the plant from 5/16/2008 until replaced with new LCR-33 cells manufactured by C&D Battery on 5/24/2008. The Technical Specifications did not require this battery bank while the plant was in Mode 6 and disconnected from the bus.

The report date for this LER exceeds 60 days from the event date because this condition is being reported as a voluntary LER to report an issue of generic interest and identification that this issue is of generic interest has recently been determined.

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		2009	- 002	- 01		

NARRATIVE**CAUSAL FACTORS**

The root cause for the Station Battery 'B' reaching approximately 85% of its rated capacity at ~ 15.6 years was unidentifiable. The possible Aging and Degradation Mechanisms identified in the EPRI Station Battery Guide for vented lead-acid batteries were all eliminated except impurities. Impurities could not be validated or eliminated since the original batteries were not quarantined and subsequently removed from site and destroyed.

The cells used in the Station Battery 'B' were manufactured by C&D Batteries in October 1992, to the same specification as the cells used in Station Batteries 'A' and 'AB'. Performance tests of Station Batteries 'A' and 'AB' also performed in Refuel 15 indicated no similar degradation had occurred.

Aging and Degradation Mechanisms identified in the EPRI Station Battery Guide for vented lead-acid batteries are reasonably well understood by the industry. The Aging and Degradation Mechanisms that will limit battery life and performance that were evaluated were Temperature, Discharge Cycle Service, Overcharging, Undercharging and Impurities.

CORRECTIVE ACTIONS

The entire Station Battery 'B' bank was replaced with LCR-33 cells manufactured by C&D Battery. The new Station Battery 'B' successfully passed post installation testing and met all operability requirements.

SAFETY SIGNIFICANCE

The Station Batteries are sized in accordance with IEEE Std 485, IEEE Recommended Practice for Sizing Large Lead Storage Batteries for Generating Stations and Substations. The sizing of the Station Batteries allows for compensation of age when actual capacity drops to 80% of manufacturers rating with an additional design margin of 10%. Based on the 'as-found' results of the initial Refuel 15 Station Battery 'B' performance test, the battery was capable of meeting the requirements of the service test that meets the design basis for operability. The Station Battery 'B' was disconnected from the bus for planned maintenance at the time of the 5/26/2008 performance test. The Station Battery 'B' was replaced prior to returning it to service.

Technical Specification limiting conditions for operation were satisfied for Mode 6 with an operable Station Battery Bank 'A' and its associated full capacity charger. There was no negative impact on the availability of systems or components needed to maintain safe shutdown conditions, remove residual heat, control the release of radioactive material, or mitigate the consequences of an accident.

Based on the above discussion, there was no increased challenge to nuclear, radiological or industrial safety.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE	
Waterford 3 Steam Electric Station	05000382	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 4	
		2009	- 002	- 01		

NARRATIVE

SIMILAR EVENTS

There have been no previous, similar licensee events reported in the last three years.

ADDITIONAL INFORMATION

Energy industry identification system (EIS) codes are identified in the text within brackets [].